MIDLITE®

QUALITY CUSTOM PRODUCTS

INSTALLATION GUIDE:

SPEEDPORT™ Universal Cable Pass Through,
Fastening & Anchor System

PN: R2SP-
2SP-

v.042815

Additional Product Numbers:

SPEEDPORT™ Includes:

Single SPEEDPORT™
R2SP-W (qty 1) (White)
R2SP-B (qty 1) (Black)
R2SP-A (qty 1) (Almond)
R2SP-LA (qty 1) (Light Almond)
R2SP-I (qty 1) (Ivory)
R2SP-BR (qty 1) (Brown)

Master pack of 5
2SP-W (qty 5) (White)
2SP-B (qty 5) (Black)
2SP-A (qty 5) (Almond)
2SP-LA (qty 5) (Light Almond)
2SP-I (qty 5) (Ivory)
2SP-BR (qty 5) (Brown)

SPEEDPORT™ (2")

Rubber Grommet

Tools Needed:

Phillips Head ⊕
Screwdriver

2" Hole Saw

Power Drill

MIDLITE®
QUALITY CUSTOM PRODUCTS

1. Using a 2" hole saw, create a hole in the wall or ceiling where the wiring should pass.

2. Feed wiring out through the opening.

www.midlite.com
115 Wordell St. Fall River, MA 02721
Tel: 508.676.5169 | Toll Free: 800.606.5169 | Fax: 508.861.0105

MIDLITE®
QUALITY CUSTOM PRODUCTS

3. Insert wiring through the SPEEDPORT™. Then with the mounting tabs tucked in, insert the SPEEDPORT™ into the opening.

4. Using a Phillips Head Screwdriver, tighten the two screws located on the inside of the SPEEDPORT™.

5. When tightened the screws, the mounting tabs will rotate into place and lock the SPEEDPORT™ against the wall.

6. Feed the wiring through the rubber grommet, align the notches on the grommet with the screw heads and push it into the SPEEDPORT™.

MIDLITE®
QUALITY CUSTOM PRODUCTS

Your SPEEDPORT™ is now installed.

MIDLITE®
QUALITY CUSTOM PRODUCTS